

ENGINFERS SURVEYORS PLANNERS SCIENTISTS

2880 TECHNOLOGY BOULEVARD WEST • PO BOX 1113 • BOZEMAN, MT 59771 OFFICE: 406-587-0721 • FAX: 406-922-6702 • www.m-m.net

RECEIVED

May 31, 2012

JUN 0 4 2012

Chris Boe Montana Department of Environmental Quality Water Protection Bureau JIP 4/12

DEQMPB PERMITTING & COMPLIANCE DIV.

P.O. Box 200901 Helena, MT 59620-0901

RE: City of Bozeman Water Treatment Plant Discharge Permit MTX000224 Monitoring well installation reporting requirements.

Dear Mr. Boe:

This letter is to fulfill the reporting requirement under section E, No. 2 of the special conditions defined under discharge permit MTX000224. These wells were installed as part of the conditions of the permit to monitor water quality parameters defined in Permit Table #3. The special conditions of the discharge permit include installation of 3 monitoring wells and a written report on the installation of the monitoring wells. Please find the attached lithologic logs, driller logs (GWIC) and well location map.

Monitoring well installation

All three monitoring wells (MW1-A, MW2-A and MW3-A) were installed by Haggerty Drilling using a dual rotary rig and direct air rotary methods. Morrison-Maierle, Inc Geologist Pat Eller was on-site during well installation and directed Haggerty Drilling on final well completion. The monitoring wells were installed in accordance with the monitoring well plan submitted to the department on February 2, 2012, and approved on February 9, 2012. Well locations were staked in the field and final location of each monitoring well is as approved in the monitoring well plan.

MW1-A

MW1-A was completed by Haggerty drilling on May 10, 2012. The well was drilled by air rotary methods using a Foremost DR-24 dual rotary drilling rig. Six inch steel casing was advanced continuously while drilling to a total depth of 76 feet. Materials penetrated by the borehole included loam, sandy clay loam and gravel. Water was first encountered at approximately 63 feet. The well was screened with 2-inch factory slotted pvc from 50 to 76 feet. The screen was sand packed with 10-20 silica sand as the casing was pulled back. Well grout consisted of bentonite chips from 46 feet to ground surface as the 6-inch steel casing was pulled back. Six inch case extends from 4 feet above ground surface to 3 feet below ground surface. Both the 2-inch well casing and the 2-inch well screens were equipped with centralizers. The well was developed using a 1 1/2' bailer. The well was disinfected on May 29, 2012.



MW2-A

MW2-A was completed by Haggerty drilling on April 30, 2012. The well was drilled by air rotary methods using a Foremost DR-24 dual rotary drilling rig. Six inch steel casing was advanced continuously while drilling to a total depth of 93 feet. Materials penetrated by the borehole included loam, loamy sand, sandy clay loam and gravel. Water was first encountered at approximately 60 feet. The well was screened with 2-inch factory slotted pvc from 48 to 93 feet. The screen was sand packed with 10-20 silica sand as the casing was pulled back. Well grout consisted of bentonite chips from 44 feet to ground surface as the 6-inch steel casing was pulled back. Six-inch case extends from 2 feet above ground surface to 3 feet below ground surface. Both the 2-inch well casing and the 2-inch well screens were equipped with centralizers. The well was developed using a 1 ½ bailer.

MW3-A

MW3-A was completed by Haggerty drilling on April 30, 2012. The well was drilled by air rotary methods using a Foremost DR-24 dual rotary drilling rig. Six inch steel casing was continuously advanced while drilling to a total depth of 68 feet. Materials penetrated by the borehole included loam, loamy sand, sandy clay loam, gravel and metamorphic bedrock. The contact between the alluvial material and the metamorphic bedrock was 65 feet below ground surface. Once bedrock was encountered, drilling was halted, the casing was pulled back and the gravel was developed with air. The gravel was determined to be drained out at this location, and drilling commenced openhole into the bedrock. Water was first encountered in a fracture set at 105 feet. Drilling proceeded to 135 feet with no increase over the initial yield of approximately 2 gpm encountered in the fracture at 105 feet.

The well was completed across the fracture within the metamorphic bedrock. The well was screened with 2-inch factory slotted pvc from 100 to 120 feet. The screen was sand packed using 10-20 silica sand as the casing was pulled back. Well grout consisted of bentonite chips from 90 feet to ground surface as the 6-inch steel casing was pulled back. Six-inch case extends from 2 feet above ground surface to 3 feet below ground surface. Both the 2-inch well casing and the 2-inch well screens were equipped with centralizers. The well was developed using a 1 ½ bailer. The well was disinfected on May 29, 2012.

Final Well Completions

Bollards were installed surrounding wells MW2-A and MW3-A to provide protection from physical damage. Bollard installation at MW1-A is planned to be competed upon establishment of final grade at the well site. All three wells are equipped with locking well caps. Wellhead elevations were surveyed after completion and are included on the attached lithologic logs.



Sampling

Sampling and reporting requirements of the discharge permit will be provided by City of Bozeman personnel and will follow the conditions of the permit.

If you have any questions or comments on the completion of the monitoring wells or this report please feel free to reach me at (406) 922-6769 or neller@m-m.net.

Sincerely,

A MORRISON-MAIERLE, INC.

Pat Eller

Project Geologist

Enclosure

cc: Rick Moroney, City Water Treatment Plant Superintendent

Bob Murray, City Engineering – Email Copy Dan Harmon, HDR Engineering – Email Copy

N:\2105\057\Discharge Permit\Monitoring well report.docx

RECEIVED
JUN 0 4 2012

DEQWPB PERMITTING & COMPLIANCE DIV.

MONTANA WELL LOG REPORT

Other Options

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Plot this site on a topographic map

Site Name: CITY OF BOZEMAN - WATER TREATMENT

PLANT

GWIC Id: 265706

Total Depth: 76 Static Water Level: 54 Water Temperature:

Section 7: Well Test Data

Section 1: Well Owner

Owner Name

CITY OF BOZEMAN - WATER TREATMENT PLANT

Mailing Address

7022 SOURDOUGH CANYON RD

City State Zip Code **BOZEMAN** MT 59715

Well Address

7022 SOURDOUGH CANYON RD

City State Zip Code **BOZEMAN** MT 59715

Air Test *

3 gpm with drill stem set at 71 feet for 1 hours.

Time of recovery 1 hours. Recovery water level 54 feet. Pumping water level feet.

* During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.

Section 2: Location

Township Range Section **Quarter Sections** 03S 06E SE1/4 SE1/4 SE1/4 County Geocode

GALLATIN

Longitude Geomethod Latitude Datum NAD83 45.59886635345 111.021832054 TRS-SEC

Ground Surface Altitude

Date Method Datum

Addition

Block

Lot

Section 9: Well Log **Geologic Source**

Section 8: Remarks

Unassigned

MW1A

From	То	Description
0	13	OVERBURDEN/FILL
13	15	TOPSOIL
15	76	GRAVEL

Section 3: Proposed Use of Water

MONITORING (1)

Section 4: Type of Work Drilling Method: ROTARY

Section 5: Well Completion Date

Date well completed: Thursday, May 10, 2012

Section 6: Well Construction Details

Borehole dimensions From To Diameter 0 76

Casin	2

From	То	Diameter	Wall Thickness	Pressure Rating	Joint	Туре
-3.5	3	6	0.25		WELDED	A53B STEEL
-3	50	2			FLUSH THREAD	PVC- SCHED 40

Completion (Perf/Screen)

From	То		 Size of Openings	Description
50	76	2	เกวก เ	SCREEN- CONTINUOUS-PVC

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: KEVIN HAGGERTY

Company: KEVIN HAGGERTY DRILLING INC

License No: MWC-94

Date 5/10/2012

Completed:

From	То	Description	Cont. Fed?	
-1.5	0	BENTONITE	Υ	
0	46	BENTONITE	Υ	
46	76	10-20 SAND	Υ	

MONTANA WELL LOG REPORT

Other Options

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Plot this site on a topographic map

Site Name: CITY OF BOZEMAN - WATER TREATMENT

PLANT

GWIC Id: 265702

Section 1: Well Owner

Owner Name

CITY OF BOZEMAN - WATER TREATMENT PLANT

Mailing Address

7022 SOURDOUGH CANYON RD

City **BOZEMAN** State MT

Zip Code 59715

Well Address

7022 SOURDOUGH CANYON RD

County

Ground Surface Altitude

City **BOZEMAN** State

Zip Code 59715

MT

Section 2: Location

Township 03S

Range 06E

Section

Quarter Sections SE1/4 SE1/4 SE1/4

Geocode

GALLATIN

Latitude 45.59886635345

Longitude 111.021832054 Geomethod Datum TRS-SEC

NAD83 Method Date Datum

Addition

Block

Lot

Section 3: Proposed Use of Water

MONITORING (1)

Section 4: Type of Work

Drilling Method: ROTARY

Section 5: Well Completion Date

Date well completed: Monday, April 30, 2012

Section 6: Well Construction Details

Borehole dimensions

From	То	Diameter
0	93	6

Casing

From	То	Diameter	Wall Thickness	Pressure Rating	Joint	Туре
-3	3	6	0.25		WELDED	A53B STEEL
-2.5	48	2			FLUSH THREAD	PVC- SCHED 40
88	93	2			FLUSH THREAD	PVC- SCHED 40

Completion (Perf/Screen)

			# of	Size of	
From	Τo	Diameter	Openings	Openings	Description

Section 7: Well Test Data

Total Depth: 93 Static Water Level: 52

Water Temperature:

Air Test *

1 gpm with drill stem set at 88 feet for 1 hours.

Time of recovery 1 hours. Recovery water level 52 feet. Pumping water level _ feet.

* During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.

Section 8: Remarks

MW2A

Section 9: Well Log **Geologic Source**

Unassigned

From	To	Description
0	1	GRAVEL FILL
1	3	BLACK TOPSOIL
3	26	CLAY
26	93	GRAVEL
*CHIECONA SUCCE	947021 <u>11.0000000000</u>	
L	L	fication

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: KEVIN HAGGERTY

Company: KEVIN HAGGERTY DRILLING INC

License No: MWC-94

Date 4/30/2012

Completed:

48	88	2		.020	SCREEN- CONTINUOUS-PVC
Annul	ar S	Space (Seal/C	irout/P	acker)	
			Cont.		
From	То	Description	Fed?		
-1.5	0	BENTONITE	Υ		
0	44	BENTONITE	Υ		
44	93	10-20 SAND	Υ		

MONTANA WELL LOG REPORT

Other Options

This well log reports the activities of a licensed Montana well driller, serves as the official record of work done within the borehole and casing, and describes the amount of water encountered. This report is compiled electronically from the contents of the Ground Water Information Center (GWIC) database for this site. Acquiring water rights is the well owner's responsibility and is NOT accomplished by the filing of this report.

Plot this site on a topographic map

Site Name: CITY OF BOZEMAN - WATER TREATMENT PLANT Section 7: Well Test Data GWIC Id: 265697

Section 1: Well Owner

Owner Name

CITY OF BOZEMAN - WATER TREATMENT PLANT

Mailing Address

7022 SOURDOUGH CANYON RD

City **BOZEMAN** State MT

Zip Code

59715

Section 2: Location

Township 03S

Range 06E

County

Ground Surface Altitude

Section

Block

Quarter Sections SE1/4 SE1/4 SE1/4

Geocode

GALLATIN

Addition

Latitude 45.59886635345

Longitude 111.021832054 Geomethod TRS-SEC

NAD83 Datum

Method

Lot

Total Depth: 120 Static Water Level: 60.5 Water Temperature:

Air Test *

1 gpm with drill stem set at 115 feet for 1 hours.

Time of recovery 1 hours. Recovery water level 60.5 feet. Pumping water level _ feet.

* During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.

Section 8: Remarks

MW3A

Datum

Date

Section 3: Proposed Use of Water MONITORING (1)

Section 4: Type of Work

Drilling Method: ROTARY

Section 5: Well Completion Date

Date well completed: Wednesday, April 25, 2012

Section 6: Well Construction Details

Borehole dimensions From To Diameter 0 120

Casing

			Wall	Pressure		
From	То	Diameter	Thickness	Rating	Joint	Туре
-3	3	6	0.25		WELDED	A53B STEEL
-2.5	100	2			FLUSH THREAD	PVC-SCHED 40

Completion (Perf/Screen)

From	То		 Size of Openings	Description
100	120	2	.020	SCREEN-CONTINUOUS- PVC

Annular Space (Seal/Grout/Packer)

			Cont.
From	То	Description	Fed?
-2	0	BENTONITE	Υ
0	90	BENTONITE CHIPS	Υ
90	120	10-20 SAND	Υ

Section 9: Well Log **Geologic Source**

Unassigned

From	То	Description
0	4	TOPSOIL
4	32	CLAY
32	65	GRAVEL
65	78	BEDROCK, BLACK METAMORPHIC
78	120	DECOMPOSED GRANITE
220000000000000000000000000000000000000		

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: KEVIN HAGGERTY

Company: KEVIN HAGGERTY DRILLING INC

License No: MWC-94 Date Completed: 4/25/2012





